

Thermo printer

Changing interface: RS232 to Bluetooth



loosen the 2 screws



remove the RS232 slot





insert the Bluetooth slot
Art. No. JB01-BT Modul SLK-TE25
your verification number for Bluetooth





tighten the Bluetooth slot with 2 screws

Configuration WATCH EXPERT


First insert the Bluetooth Dongle in the WATCH EXPERT USB port.







Configuration Chronoscope X1 (G3) with Firmware V1.1.0 or later versions



First insert the Bluetooth Dongle in the Chronoscope X1 (G3) USB port.






Configuration Chronoscope S1 (G2) with Firmware V2.2 or later versions

First insert the Bluetooth Dongle in the Chronoscope S1 (G2) USB port.





  select your verification number for Bluetooth

Connection to Witschi devices with Bluetooth



WisioScope S

WATCH EXPERT

Chronoscope X1 (G3)

Chronoscope S1 (G2)

Connection to Witschi devices with RS232

For Witschi devices:

- Analyzer Twin
- Analyzer Q1
- Analyzer Q2
- Newtech Handy II
- Chronoscope S1 (G1)
- Chronoscope S1 (G2)
- Chronoscope M1
- Watch Expert III
- Proofmaster S
- Proofmaster M
- Qualimaster

=



Interface cable



JB01-SLK-TE25-S



WATCH EXPERT



Chronoscope X1
Chronoscope X1 (G2)
Chronoscope X1 (G3)

=



GA05-E715251

and



Interface cable



WisioScope S